

RECEIVED

JAN 17 2000

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING  
1594 West North Temple - Suite 1210  
Box 145801  
Salt Lake City, Utah 84114-5801  
Telephone: (801) 538-5291  
Fax: (801) 359-3940

DIVISION OF OIL, GAS & MINING

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 1-1-99 To (mo./yr.) 1-1-2000
  2. DOGM File Number (Mine No): M/43/021
  3. Mine Name: BROWNS CANYON ROCK QUARRY
  4. Mineral(s) Mined (or permitted to mine): SANDSTONE
  5. Type of mine ☒ Surface Mine or ☐ Underground Mine
  6. Legal Description (Location of Lands Affected):  
SW 1/4, NW 1/4, \_\_\_ 1/4, Section 21, Township 1 S., Range 5 E.  
NW 1/4, SW 1/4, \_\_\_ 1/4, Section 21, Township 1 S., Range 5 E.  
\_\_\_ 1/4, \_\_\_ 1/4, \_\_\_ 1/4, Section \_\_\_, Township \_\_\_, Range \_\_\_
  7. Name of Operator or Company: BMW Stone Inc
  8. Permanent Street Address: 7125 South 300 East  
City, State, Zip: Midvale, UT 84047  
Phone: \_\_\_\_\_ Fax: \_\_\_\_\_
  9. Company Representative (or designated operator):  
Name: Mark Willes  
Title: Vice President  
Business Address: 7125 So 300E  
City, State, Zip: Midvale, UT 84047  
Phone: 801-562-0852 Fax: 801-562-3058
- ☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was there any mine related activity during the past year? Yes ☒ No ☐
2. If no - what was the last year of activity? \_\_\_\_\_
3. If yes - how much ore or mineral was mined? 10,000 cubic yards sold 5000 cubic yards in tailing piles to be crushed at a later date

4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.

stone is dug out and split into Building stone.  
approximately 15,000 Cubic yards of material was  
moved. We went over the 5 acre limit and applied  
for a large mining permit

5. How much **additional acreage** was disturbed during the past year? 1.4

6. How much acreage was **reclaimed** during the past year? 0

7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

all areas are still being used, reclamation  
will be done when mining of ore body is completed

8. What is the **total** disturbed acreage of entire project at years end? 6.4 acres

9. Briefly summarize any mining and/or reclamation plans for the upcoming year.

an application for a large mining permit  
is in the works

**NOTE:** Section III, "Additional Information" applies only to **large mining operations**.

### III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

### IV. Signature Requirement

**I hereby certify that the foregoing is true and correct.**

Name (Typed or Print):

MARK WILLES

Title of Operator:

VICE PRESIDENT

Signature of Operator:

Mark Willes

Date:

1 - 4 - 2000